

From: [Matt Wickham](#)
To: [Josiam, Raji](#)
Subject: RE: USOR - Estimated Timeframe for the rest of the samples
Date: Wednesday, November 23, 2016 11:54:54 AM
Attachments: [removed.txt](#)
[FIG 1 - Sample Location Map \(Option 2\).pdf](#)

Raji – a few months ago when it was clear that the completion of the removal actions would be delayed by several months, we decided to go ahead with the sampling around the equipment and tank farm. By moving a few locations we were able to access all but one planned soil sample location. Those samples were collected during Mobilization 3 (August 29-31). The data from those samples has been validated and is in the database recently sent to you with the bi-monthly report. The base map that was attached to the bi-monthly report also shows the samples that have been collected (attached again here).

We are currently developing a WRN that will propose additional data collection on-property. That will be submitted to EPA within the next couple of weeks. Assuming EPA acceptance of the WRN, we would then go collect the additional data shortly thereafter. After those data are validated, we propose a meeting with EPA to discuss all of the data that has been collected and decide on the following two items: 1) any revisions to the proposed RI/FS Work Plan locations for on-property groundwater monitoring wells based on the data collected; and 2) any revisions to the off-property soil sampling locations that were proposed in the RI/FS Work Plan.

Please contact me with any questions.

Regards,

Matt

From: Josiam, Raji [mailto:josiam.raji@epa.gov]
Sent: Wednesday, November 23, 2016 10:21 AM
To: Matt Wickham
Subject: USOR - Estimated Timeframe for the rest of the samples
Matt

I heard from Adam that the as of now the removal work for equipment and AST removal will take until January. Just wanted to touch base to see if you have an estimated time frame for taking the rest of the samples in the equipment area along the fence line and the AST area.

Raji Josiam

Remedial Project Manager

US EPA Region 6

1445 Ross Ave, Suite 1200, 6SF-RA

Dallas, TX 75202

Email: josiam.raji@epa.gov

Direct: 214-665-8529

Fax: 214-665-6660

Superfund: 1-800-533-3508



***** ATTACHMENT REMOVED

This message contained an attachment which the administrator has caused to be removed.

***** ATTACHMENT REMOVED

Attachment name: [image001.jpg]
Attachment type: [image/jpeg]